

SUNLAND WATER DISTRICT

Commissioners Meeting

November 2019

Manager's Report by Mike Langley

~~~~~  
~~~~~

Financial Report by Karen Shay

Water Reclamation Facility

- Reclaimed water filter number two is now clean and ready to use.
- The class "A" reclaimed water pump has been repaired.
- Willy and Rich are completing some far overdue remodeling and re-organizing at the WRF lab.

Water Meters/Meter Setters

- This is our month off for meter reading. The next water meter read is planned for the first week in December.

Water Production/Consumption Results

- The water level in both wells now is the same as it was in January.

- Total water production for September of 2019 from both sources was 7,252,088 gallons, for a total water production in 2019 of 79,899,085 gallons.

Other

- The sewer lift station replacement went smooth and was completed in one day. The City of Sequim staff performed very well for cleaning out the lift station prior to equipment removal and then moved to an upstream manhole to keep inflow from getting to the work site. SWD personnel used our sludge truck to keep another upstream manhole clear.

Jason of Groves Crane removed the new lift station and placed it on the existing wet well. He had to do that three times to allow the installers to get all the plumbing completed.

JT of Straits Electric was here all day disconnecting power then reconnecting power and making other wiring changes for the new equipment.

Representatives from Smith & Loveless were on site along with the installation team who all did a super job of communicating and coordinating with each other as well as other participants to make the job go smoothly and efficiently.

We are working with the alarm supplier to get that system changed over and operational.

- The 199 Sunset Place street bore/water & sewer connections are complete.
- Another request for information from the party on Cascadia Loop. Judy responded to them and I forwarded the request to our attorney.
- SWD received an inquiry about a damaged sewer line in Division 17 East.

The problem is between a 4" cleanout and the District's 6" cleanout. This places the issue outside the Districts responsibility.

