



Commissioner's Meeting JULY 21, 2026

MANAGERS' REPORT BY ROBERT WHALEN

Water Reclamation Facility

- All equipment maintenance has been completed
- 86 tons of Round Bales were harvested off the field
- New composite sampler has arrived
- New Brawn Alum Mixer has arrived
- Site inspection for permit renewal was conducted by DOE
- Quarterly well monitoring has been done

Water

- Water service leak at 188 San Juan (7/5/26). Water leak was on the service line in customer's yard. Estimated water loss is 4,000 gallons.
- Water service leak at 180 San Juan (7/7/26). Water leak was on service line out in lane of traffic. Estimated water loss of 21,000 gallons.
- Water service leak at 102 Northwestern Pl (7/14/26). Leak was on service line in cul-de-sac. Estimated water loss of 11,000 gallons
- Water loss for the month of June was 4%, down from 5% last month. Static levels for June rest at 100.0, .04 ft lower than last month, while the pumping levels are at 126 ft, 1 ft lower than last month.